

Find the optimum cutting speed (v) and feed (f_r) based on minimum production time using the Taylor-type tool life equation?